



INTRODUCTION

Evolis is conducting for many years a general policy to improve the quality and features of his printer range. This document describes modifications and improvements from original firmware release 1426 to the latest available from Badgy website version 1759 released on August 2021.

SUMMARY

Related printers' models:

- Badgy 100
- Badgy 200

VERSION HISTORY	2
Firmware version – 2126 (74CD)	2
Firmware version – 1759 (2996)	2
Firmware version – 1757 (534F)	2
Firmware version – 1754 (CB62)	2
Firmware version – 1634 (9C62)	2
Firmware version – 1631	2
Firmware version – 1626	2
Firmware version – 1624	2
Firmware version – 1605	3
Firmware version – 1504	3
Firmware version – 1443	3
Firmware version – 1426	3

VERSION HISTORY

02/11.2021

Firmware version – 2126 (74CD)

- New configurable auto-sensor adjustment

09/08/2021

Firmware version – 1759 (2996)

- Cam sensor detection improved.

04/12/2020

Firmware version – 1757 (534F)

- Firmware version alignment

13/05/2020

Firmware version – 1754 (CB62)

- Cleaning warning management (Pcsc / Rcsc added commands)
- Power supply voltage control (when power on printer)
- Ribbon management improvement (enable/disable ribbon synchronization when power on or exit from standby mode)
- Color (YMC) panel's contrasts improvement.

04/07/2017

Firmware version – 1634 (9C62)

- Ribbon management improvement.

16/12/2016

Firmware version – 1631

- Pre-heating mode improvement
- Internal memory data backup improvement

06/09/2016

Firmware version – 1626

- Varnish quality improvement.

06/07/2016

Firmware version – 1624

- Print head temperature regulation improvement.
- Print head signal management improvement.

18/02/2016

Firmware version – 1605

- Color sensor adjustment process improvement.
- USB communication improvement.
- Technical test card printing process improvement.
- Add monochrome speed management.

02/02/2015

Firmware version – 1504

- Sleep mode disable by default.
- USB device communication improvement (USB Certification OK).
- Color sensor adjustment improvement.
- Add automatic color readjustment if the ribbon synchronisation failed.

30/10/2014

Firmware version – 1443

- Black printing quality improvement (for color ribbon).
- Set USB to USB 2.0 full speed (USB Certification agreement).
- Design modification of the Technical Card (Internal font change).

26/05/2014

Firmware version – 1426

- Original firmware version.

EUROPE - MIDDLE-EAST - AFRICA

Evolis - 14 avenue de la Fontaine - ZI Angers-Beaucouzé
49070 Beaucouzé - France
T +33 (0) 241 367 606 - F +33 (0) 241 367 612
info@evolis.com

AMERICAS - Evolis Inc. - Fort Lauderdale - evolisinc@evolis.com

ASIA-PACIFIC - Evolis Asia Pte Ltd - Singapore - evolisasia@evolis.com

CHINA - Evolis China - Shanghai - evolischina@evolis.com

INDIA - Evolis India - Mumbai - evolisindia@evolis.com